United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form



code]

See instructions in *How to Complete National Register Forms* Type all entries—complete applicable sections

1. Name

historic Saragossa

and/or common Saragossa

2. Location

state Mississippi code 28 county Adams

3. Classification

Category	Ownership	Status	Present Use	
district	public	x_ occupied	agriculture	museum
X_ building(s)	x_ private	unoccupied	commercial	park
structure	both	work in progress	educational	<u>X</u> private residence
site	Public Acquisition	Accessible	entertainment	religious
object	in process	yes: restricted	government	scientific
	being considered	yes: unrestricted	industrial	transportation
		_ <u>X_</u> no	military	other:

4. Owner of Property

name Mrs. Mamie F. Smith, Mrs. Routh Smith Crowell, Mrs. Mamie Smith Hammett, Mr. Austin W. Smith, Mr. Walton P. Smith, and Mrs. Katherine Smith Wickliffe street & number Route 3, Box 81

city, town	Natchez	q		_x_ vicinity of		state M	<u>lississi</u>	i 3	9120
5. Le	ocatio	n of	Legal	Descriptio	on				
courthouse	e, registry of de	eds, etc.	Adams Cou	nty Courthouse					
street & nu	mber Cour	thouse	Square						<u> </u>
city, town	Natchez					state	Missis	sippi	39120
6. R	eprese	entat	ion in	Existing S	Surveys				
title				has this pro	perty been deterr	nined el	egible?	yes	no
date					federal	stat	te co	ounty	local
depository	for survey rec	ords							

city, town

7. Description

Describe the present and original (if known) physical appearance

Saragossa, which is located about five miles south of Natchez, is approached from a gravel drive which begins at the terminus of Saragossa Road, a paved road that is marked and is entered to the east of the Old Woodville Road. The one-story brick house, which is set upon a basement that is fully raised on the facade, features a gable roof with high shed-roof attachments on all four sides. An inside-end chimney is located at each gable end of the house, a chimney pierces the rear slope of the roof, and two outside-end chimneys are located on the clapboard wall of the enclosed rear gallery. Double-tiered galleries, partially enclosed, encircle the entire house. The galleries are supported on the basement level by brick piers which were originally stuccoed but rebuilt in the 20th century with exposed brick, and on the main level by wooden box columns with molded capitals that are linked by lengths of chain. The basement level galleries on the rear and side elevations toward the rear of the house exist in the form of moat-like channels with a flight of steps rising from each side channel in a southeasterly direction into the back yard. The upper and lower galleries are connected by a flight of stairs rising in a single straight flight in a northwesterly direction on the northeast side of the house. The main floor gallery is partially unfloored on the northeast side of the house and partially floored with metal bars on the southwest side to provide light in the basement gallery moats.

Saragossa has undergone at least two major remodelings, one in the 1830's and the other in the mid-19th century, since its original construction in the early 19th century. The main level, northwesterly facade, which is divided into three slightly asymmetrical bays, is finished with a molded base, and the entrance doorway, which is raised two steps from the level of the gallery floor, is located in the centermost bay. This entrance doorway consists of a four-paneled and molded door which dates to the 1830's and is matched by the two exterior doors opening into the basement dining room. Two additional matching doors and two, finely detailed, wooden mantel pieces of the 1830's period have been reused in the one surviving slave quarters building and were probably originally located in the main house. After the acquisition by the Smith family in 1855, Saragossa underwent its most extensive remodeling. The main rear gallery was totally enclosed and the basement rear gallery partially enclosed. The main floor became T-shaped in plan with double parlors in the original brick portion and two bedrooms separated by a sitting room/hallway in the rear frame enclosure. The basement area of the original brick portion became a large formal dining room and the moat-like rear gallery was enclosed into two smaller rooms, presently a kitchen and pantry. Two small pantry rooms were built at the rear corners of the basement gallery providing additional support for the bedroom additions of the main floor. The brick original structure and the rear mid-19th century frame additions were given a harmonious appearance by the application of scored stucco on all but the rear elevation which was finished with clapboards. All windows of the main floor facade and side elevations contain large, six-over-six, double-hung sash, and almost all door and window openings are closed with mid-19th century shutter blinds.

The two-bay basement facade features casement windows with jib doors which are echoed inside the basement dining room by built-in china cabinets in the gable-end walls. The basement dining room is floored with a highly polished cement, the mantel piece is wooden and pilastered, and the surrounds and bases are unmolded. The enclosed rear gallery rooms of the basement feature board-and-batten doors and one mid-19th century wooden mantel piece with shouldered architrave that matches the mantel pieces, one removed, of the main floor bedrooms. The double parlors feature sliding doors in a shouldered architrave surround and marble mantel pieces, one of which has been removed. All bases of the principal floor are molded with a single fascia, and the doors of the mid-19th century remodeling are four-paneled and molded.

An original frame slave quarters, in deteriorated condition, is located to the rear of the south corner of the main house and features a gabled roof with central chimney, gallery, and two-bay facade.

8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agriculture X architecture art commerce communications Early 19th century;	community planning conservation economics education engineering exploration/settlement	Iandscape architecture Iaw Iiterature Iiterature Iitary IIItary IIIItary IIIItary IIII IIII IIIII IIIII IIIII IIIII IIIII	e religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	ca. 1830; mid-19th c.	Builder/Architect		

Statement of Significance (in one paragraph)

Saragossa is an unusual and outstanding example of an early vernacular residence of the Natchez area. Its architectural style reflects the West Indian influence that characterized the architecture of the Natchez region in the late eighteenth and early nineteenth centuries and influenced the development of regional architecture well into the nineteenth century. Although historians unfamiliar with the unique history of Natchez often characterize such buildings as Spanish in architectural character (Spain having governed Natchez from 1779 unti 1798), the West Indian tradition is substantiated historically. Two unrelated travellers, in 1808 and 1809, remarked in published accounts on the similarity between Natchez and St. John's, Antigua, and, since Natchez was governed by countries who also had outposts in the West Indies and was commercially linked to these West Indian outposts, this similarity in architectural style is understandable. Saragossa and the House on Ellicott's Hill, a National Historic Landmark constructed 1798-1802, are unique among Natchez residences evidencing this West Indian character, because they are the only extant buildings that feature a gabled roof with high, shed-roof attachments on all four sides. A feature of Saragossa thought to be unique are the mid-19th century casement windows with jib doors located in the northwesterly basement facade. The actual date of construction for Saragossa is unknown. Stylistically and historically, the house appears to have been originally constructed early in the 19th century, although all interior millwork dates to after 1830 with the exception of one pair of interior doors with glazed upper panels that are located in the basement level. Architectural investigation of the history of the house's construction is hampered by the plain, unmolded door and window surrounds found almost universally throughout the house. However, the slightly asymmetrical fenestration of the facade and side elevations, the shape of the roof, the construction techniques, the proportions of the house, and an 1826 survey map depicting the house and eight slave quarters buildings to the rear (Adams County Deed Book HH;71) all unite to support a construction date in the early 19th century. Saragossa was probably constructed as an overseer's house and later renovated to become a major family residence. Supporting this assumption are the unmolded door and window surrounds, the indications that the house possibly originally faced the eight slave quarters buildings, the proximity of the quarters buildings to the main house as evidenced in the 1826 survey map and by the surviving quarters building, and the ownership of Saragossa by wealthy planters Stephen Duncan (1823-1835) and William St. John Elliot (1835-1849; 1855) who had substantial residences closer to town. Although the house appears to have undergone at least two major remodelings in the 1830's and the mid-19th century, its pre-Civil War integrity is intact. Saragossa has been owned by the same family since 1855, when the house became the residence of Walton and Anna Williams Smith (Deed Book KK:312; KK:440), and its collection of mid-19th century furnishings and family memorabilia is outstanding.

9. Major Bibliographical References

Adams County, Missi	ssippi. Chancery Cle	erk. Deed Books N, V	/, HH, II, KK.
Adams County, Missi	ssippi. Chancery Cle	erk. Will Book 1.	
<u>Adams Countv, Missi</u>	ssippi. Circuit Cler	rk. Marriage Book 6.	
10. Geogra	phical Data	ITM NOT VE	DIEIEN
Acreage of nominated pro Quadrangle name <u>Kings</u> UMT References	· · · ·	CREAGE NOT VERIF	drangle scale1:62,500
A 11 5 6 51 1 81 11 Zone Easting	5 31481501010 Northing	B L L L L L L L L L L L L L L L L L L L	Northing
C] [] E] [] G] []		┍└┰┤└╽╻╻ ╒└┰┤└╽╻╻ н└┰┤└╽╻╻	
ght angle corners and	equal sides of 600 f	feet each with the ce	ty forms a four-sided figure w enter being the center point o lel to the walls of the house.
List all states and cour	nties for properties overla	pping state or county bo	oundaries
state	code	county	code
state	code	county	code
organization Historic	Natchez Foundation		otember 14, 1980
street & number P . 0.	Box 1761	telephone	(601) 442-2500
		state Mi	ississippi 39120
city or town Natchez			
city or town Natchez 12. State H The evaluated significance nationa As the designated State Hi 665), I hereby nominate thi	e of this property within the st al state istoric Preservation Officer fo is property for inclusion in the	tate is: $\frac{\chi}{}$ local or the National Historic Prese e National Register and certi	
city or town Natchez 12. State H The evaluated significance nationa As the designated State Hi 665), I hereby nominate thi	e of this property within the st al state istoric Preservation Officer fo is property for inclusion in the nd procedures set forth by the	tate is: $\frac{\chi}{}$ local or the National Historic Prese e National Register and certi	ervation Act of 1966 (Public Law 89– ify that it has been evaluated I Recreation Service.
city or town Natchez 12. State H The evaluated significance nationa As the designated State Hi 665), I hereby nominate thi according to the criteria and State Historic Preservation	e of this property within the st al state istoric Preservation Officer fo is property for inclusion in the nd procedures set forth by the	tate is: $\frac{X}{}$ local br the National Historic Prese e National Register and certi e Heritage Conservation and \mathcal{L}	ervation Act of 1966 (Public Law 89– ify that it has been evaluated I Recreation Service.





Saragossa Natchez Vicinity, Adams County, Mississippi Austin W. Smith, Route 5, Box 88, 100 Natchez, Mississippi 39120 August, 1980 20 Facade or northeast elevation 20 **286**

NOV 2 4 1980



Saragossa Natchez vicinity, Adams County, Mississippi Austin W. Smith, Route 5, Box 88,

20

88

Austin W. Smith, Route 5, Box 88, Natchez, Mississippi 39120 August, 1980 Southwest elevation NOV 2 A 1980

2/3



Saragossa Natchez vicinity, Adams County, Mississippi Austin W. Smith, Route 5, Box 88, Natchez, Mississippi 39120 August, 1980 Rear or southeast elevation 1980

001

2

20

NOV 2 4 1980

