NPS Form 10-900
(Rev. 8-86)

OMB No. 1024-0018 1102

United States Department of the Interior
National Park Service

National Register of Historic Places Registration Form

RECEIVED
JUL 23 1991
NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines for Completing National Register Forms* (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

1. Name of Property

historic name Tanglewood

other names/site number

2. Location

street & number County Road 468, 1 mi North of State Hwy. 48 n/a not for publication

city, town Magnolia [X] vicinity

state Mississippi code MS county Pike code 113 zip code 39652

3. Classification

Ownership of Property	Category of Property	Number of Resources within Property	
		Contributing	Noncontributing
[X] private	[X] building(s)	2	2 buildings
[ ] public-local	[ ] district		sites
[ ] public-State	[ ] site		structures
[ ] public-Federal	[ ] structure		objects
	[ ] object	2	2 Total

Name of related multiple property listing: n/a

Number of contributing resources previously listed in the National Register 0

4. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act of 1966, as amended, I hereby certify that this [X] nomination [ ] request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property [X] meets [ ] does not meet the National Register criteria. [ ] See continuation sheet.

Kenneth H. O'Dell — July 18, 1991

Signature of certifying official — Date

Deputy State Historic Preservation Officer

State or Federal agency and bureau

In my opinion, the property [ ] meets [ ] does not meet the National Register criteria. [ ] See continuation sheet.

Signature of commenting or other official — Date

State or Federal agency and bureau

5. National Park Service Certification

I, hereby, certify that this property is:

[X] entered in the National Register.
[ ] See continuation sheet.
[ ] determined eligible for the National Register. [ ] See continuation sheet.
[ ] determined not eligible for the National Register.
[ ] removed from the National Register.
[ ] other, (explain:) _____

Entered in the National Register

Helen Byers — 8/23/91

for Signature of the Keeper — Date of Action

6. Function or Use

Historic Functions (enter categories from instructions)	Current Functions (enter categories from instructions)
Domestic: single dwelling	Domestic: Single dwelling

7. Description

Architectural Classification (enter categories from instructions)	Materials (enter categories from instructions)
Greek Revival	foundation Brick walls Weatherboard roof Asphalt other N/A

Describe present and historic physical appearance.

Tanglewood is located on a four-acre rural tract of land on the western side of Pike County Road #468, less than one mile north of its intersection with State Highway 48. Accessed from the county road by a circular graveled drive, Tanglewood is a two-and-a-half story, frame Greek Revival house that originally rested upon stone piers, later replaced on the perimeter by a brick foundation wall. The house is sheltered by a gabled roof that is pierced on the front slope by two gabled dormers dating to ca. 1940. The house is flanked at each gable end by an outside chimney featuring cap detailing and buttressed bases that are common to pre-Civil War houses in neighboring Amite County. A double-tiered gallery extends the full-width of the facade and is sheltered beneath the broken slope of the roof. The gallery is supported on both levels by wooden posts linked by a railing of rectangular-sectioned balusters; the first-story gallery floor has been reconstructed in concrete. The gallery posts are shallow in profile but wide in front to give the appearance of a box column. Both stories of the easterly facade are matching and are finished in horizontal tongue-and-groove boards with a baseboard. The facade is a six-bay, symmetrical composition with each three- bay half containing an entrance doorway flanked by windows (w-d-w-w-d-w). The doorway and window openings of the facade have narrow, unmolded surrounds with corner blocks. All windows of the house are filled with six-over-six, double-hung sash and are closed by shutterblinds, except for the attic windows which are filled with four-over-four double-hung sash. The entrance doorways are filled with eight-light transoms (arranged in two tiers of four lights) atop single-leaf, molded four-panel doors.

The interior plan is a double-pile plan, two rooms across, with no central hallway. The interior door and window surrounds feature narrow unmolded surrounds with diminutive corner blocks identical to the Hampton Lea House in Amite County. Baseboards have two fascias and are unmolded. Interior doors are two-paneled and molded and set beneath four-light transoms. All interior mantel pieces but one are original and they are simple and pilastered.

[x] See continuation sheet

8. Statement of Significance

Certifying official has considered the significance of this property in relation to other properties:

☐ nationally ☐ statewide ☒ locally

Applicable National Register Criteria ☐ A ☐ B ☒ C ☐ D

Criteria Considerations (Exceptions) ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Areas of Significance (enter categories from instructions)	Period of Significance	Significant Dates
Architecture	ca. 1850	ca. 1850

Cultural Affiliation

N/A

Significant Person

N/A

Architect/Builder

unknown

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

Tanglewood is a vernacular Greek Revival plantation house that derives regional distinction from its two-and-a-half story form, double-tiered porch, and matching first and second-story facades. Tanglewood exhibits stylistic details that relate closely to surviving pre-Civil War houses in neighboring Amite County. The close similarity between the Pike County's Tanglewood and Amite County's 1859 Hampton Lea House (Hampton Lea House, Amite County, National Register File, Mississippi Department of Archives and History, Jackson) indicate that both houses were probably the work of the same builder. Both Tanglewood and Hampton Lea houses feature door and window surrounds with narrow unmolded facings and diminutive corner blocks, matching stairways, and transomed interior doorways. Additional architectural details shared by Tanglewood and most pre-Civil War houses in Amite County include exterior chimneys with buttressed bases and capitals with cornice and frieze band, log or stone piers, gallery posts that are made to resemble box columns in width but are shallow in profile, and flush board walls instead of plaster. Tanglewood was built as the residence of Joel Jackson Coney (Pike County Records were destroyed by fire ca. 1882). The overall integrity of the house is good with significant alterations limited to the replacement of one original mantel piece, the installation of roof dormers and a concrete gallery floor, and the 1980's addition of a rear, one-story wing.

☐ See continuation sheet

9. Major Bibliographical References

Bagley, CLinton, refernece librarian with Washington County Public Library, Greenville, Mississippi. Inspection of Tanglewood, October 1989.

Mississippi Department of Archives and History, Jackson, National Register File Amite County. Hampton Lea House

Mississippi New and Views. " The Story of Tanglewood," by Edyth McCraw. February,1973. pp. 14-16.

☐ See continuation sheet

Previous documentation on file (NPS):

- ☐ preliminary determination of individual listing (36 CFR 67) has been requested
- ☐ previously listed in the National Register
- ☐ previously determined eligible by the National Register
- ☐ designated a National Historic Landmark
- ☐ recorded by Historic American Buildings Survey # _____
- ☐ recorded by Historic American Engineering Record # _____

Primary location of additional data:

- ☒ State historic preservation office
- ☐ Other State agency
- ☐ Federal agency
- ☐ Local government
- ☐ University
- ☐ Other

Specify repository: Mississippi Department of Archives and History, Jackson, Mississippi

10. Geographical Data

Acreage of property four acres plus or minus

UTM References

	Zone	Easting	Northing		Zone	Easting	Northing
A	15	749935	3447230	B			
C				D			

☐ See continuation sheet

Verbal Boundary Description From the intersection of a wire fence said to mark the North line of Northeast Quarter of Southeast Quarter (NE¼ of SE¼), Section 15, Township 2 North, Range 8 East,Pike County, Mississippi, (and the extension thereof) with the center of the Paved Public Road; thence run South 26° 42' East for 1477.5 feet; thence run South 38°15' East for 319.4 feet to a point in the center of the above mentioned Paved Public Road for the Point of Beginning of the property herein described; thence run West 362 feet; thence

☒ See continuation sheet

Boundary Justification The nominated four-acre tract represents all of the property historically associated with Tanglewood Plantation House that is owned by the present owners

☐ See continuation sheet

11. Form Prepared By

name/title Clinton Ikerd Bagley

organization _____ date 25 February 1991

street & number P. O. Box 1332 telephone 601-334-1468

city or town Greenville state MS zip code 38702

★U.S.GPO:1988-0-223-918

The main staircase to the upper story is located in the southerly front room and features rectangular-sectioned newels and balusters. The stair runs in a northerly direction along the westerly wall to an intermediate landing, where it makes a quarter turn to continue in an easterly direction along the northerly wall. The stair terminates in the southern, second-story front room. The builder of the house provided no access between the southern and northern halves of the second story of the house. The northern half of the second story is accessed from the first story by a second staircase located in the northerly, first-story rear room. This stair, which is similar in detail to the main staircase, runs principally along the southerly wall and terminates in the rear room above. Although the second-story mantel pieces match the original of the first story, the door and window surrounds lack the corner block embellishment of the lower story.

A new, gabled-roof frame addition at the rear has been built to replace an earlier deteriorated addition. Historic dependency buildings are limited to a log crib located just northeast of the main house.

To the north of the house are two noncontributing outbuildings: a masonry well house and dairy barn, both of relatively recent construction.

(continued from form)

run South 400 feet; thence run East 604 feet; thence run Northwesterly along the center of the above mentioned Paved Public Road for 368 feet, more or less, to the Point of Beginning; less and except that portion of the above described parcel of land occupied by the right-of-way of the Paved Public Road; containing a net amount of 4.00 acres, more or less, lying partly in Southwest Quarter of Southwest Quarter (SW ¼ of SW ¼), Section 14, and partly in Southeast Quarter of Southeast Quarter (SE ¼ of SE ¼), Section 15; all in Township 2 North, Range 8 East, Pike County, Mississippi.

Photo 1 of 5

Tanglewood
Pike Co. MS
CLINTON Bagley - Photo credit
October - 1989 Negatives Miss Dept of Archives & History

Looking northwesterly, the easterly facade and South elevation

Tanglewood
Pike Co., MS
Photo Credit: Chinton Bagley
Oct. 1989
Negatives: MDAH

Looking southwesterly - North elevation + facade

Photo 3 of 5

Tanglewood

March 1990

Pike Co. MS

Photo credit: Clinton Bagley

Negatives: MDAH

Looking northwesterly

facade (east elev) and

south elevation

Tangle wood
Pike Co. MS

Photo 4 of 5
October 1989

Looking northeasterly
interior wall (North)
of South parlor

Photo credit: Clinton Bagley

NEGATIVES: MDAH

Tanglewood
Pike Co. MS.
October 1989
Photo credit: Clinton Bagley
negatives: MISS DEPT OF ARCHIVES & HIST.

Photo 5 of 5

Looking Northwesterly
South + West walls of South Parlor